

**Streambed Crossing**

Mule fat scrub removed and minor earthwork done at this location.



Looking south across streambed.



Looking north across streambed.

G:\PROJECTS\SAC-ALL\SAC-10\Photo Pages

**Streambed Crossing**

Mule fat scrub removed and minor earthwork done at this location.



Looking east along north side of streambed.



Looking west along north side of streambed.

G:\PROJECTS\SAC-ALL\SAC-10\Photo Pages

**Test Pits**



Test Pit 1



Test Pit 2

G:\PROJECTS\SAC-ALL\SAC-10\Photo Pages

**Test Pits**



**Test Pit 3**



**Test Pit 4**

G:\PROJECTS\SAC-ALL\SAC-10\Photo Pages